




M 5.7, 20km ESE of Marmaraereglisi, Turkey

Origin Time: 2019-09-26 10:59:26 UTC (Thu 13:59:26 local) Location: 40.8900° N 28.1727° E Depth: 10.0 km

PAGER Version 4

Created: 1 day, 0 hours after earthquake



Estimated Population Exposed to Earthquake Shaking

ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	462k*	8,948k*	6,220k	65k	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

^{*}Estimated exposure only includes population within the map area.

Population Exposure

population per 1 sq. km from Landscan 5000

10000

27.8°W 28.5°W Kirklareli

Structures

Overall, the population in this region resides in structures that are a mix of vulnerable and earthquake resistant construction. The predominant vulnerable building types are adobe block and dressed stone/block masonry construction.

Historical Earthquakes

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
1999-08-31	146	5.1	VI(209k)	1
2002-01-21	252	4.8	VI(97k)	1
1999-08-17	149	7.6	IX(396k)	17k

Recent earthquakes in this area have caused secondary hazards such as landslides that might have contributed to losses.

Selected City Exposure

rom GeoNames.org

MMI	City	Population
VI	Marmara Ereglisi	11k
VI	Bueyuekcekmece	163k
VI	Sultankoy	3k
٧	Selimpasa	11k
٧	Kavakli	51k
٧	Canta	5k
٧	Istanbul	11,174k
IV	Tekirdag	122k
IV	Yalova	71k
IV	Bursa	1,413k
IV	Kirklareli	58k

bold cities appear on map.

(k = x1000)

Pinarhisar		re
		b
		s
IV.		
Luleburgaz		
		ŀ
Gerkezkoey		
	~~	<u> </u>
©orlu V	N IV	
The state of the s		id 1
Canta		pr -
41.0 ° N	Istanbul	
Textiday		MI I
/ V 🖈	Aoglar	a
Balli	/ Auliv	
VI		1
IV IV		3
		<u>fr</u>
Marmara	F 1 1872	
~~		10
		E .
Bandirma	M <u>udan</u> ya	ä,

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.

Musta **(**akemalpasa